INSPECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

SITE NAME: Castle Drive Landfill LOCATION: Garland, TX SITE NUMBER: TXD980626766 SURVEY DATE: 6 / 22 / 93 INSPECTED BY: STATE FIT TAT OTHER: FLUOR DAWLE- LABORATORY: X CLPEPAOTHER
RECEIVED FROM: Firmy Williamson DATE RECEIVED: 5/20/94
SAMPLE TYPE(s):
SOIL SURFACE WATER GROUND WATER OFF / ON -site OFF / ON -site OFF / ON -site
CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological
FOLLOW UP (Y/N):
// Locate Drinking Water Sources // Keep Site Active ("N"=No Further Action) // Concur with Report Recommendations
SUMMARY: This is a review of a site inspection report for an active landfill that receives insignificant, if any, quantities of hazardous wastes.
Twelve metals were detected at above background benchmark concentrations (BBC) in on-site monitoring well samples. There are no municipal wells, and no known domestic wells that are used for drinking water, within four mile radius.
Surface water path is principal concern since Lake Ray Hubard (which serves about 1.6 million) is within 15 mile surface distance. No BBC exceedences were detected at the principal point of entry (PPE). The contaminants mercury and acetone in on-site soil samples were attributed to the site.
The site scored 22.97, insufficient for NPL consideration.
RECOMMENDATION: Concur with superfund recommendation for a NFRAP decision and notification of such to the State. Recommend that the state agency coordinate with the state water supply program for continued monitoring of this potential contamination problem.
Concurrence: Liffliam 6,16,94 ENGINEER/REVIEWER 6,17,94

9028455